
Example 6-5

Fig. E6-5 shows a 50-hp, 120-V, 1800-rpm shunt DC motor. The armature resistance is 0.1 Ω and the field resistance is 50 Ω . Assume compensating windings have completely taken care of the armature reaction. Also, ignore mechanical, core and miscellaneous losses. Initially, the motor is running a constant-torque load and draws 12 kW from the source at 1,500 rpm. Assume ϕ -I_f relation is linear. If the field resistance is increased to 60Ω using an adjustable resistance in series with the field winding, find the new steady-

state armature current and speed, as well as the power loss in the adjustable resistance.



Armature current before increasing resistance:

$$I_{a_1} = I_{L_1} - I_{f_1}$$

$$P_{in} = 12000 W = V_L I_{L_1}$$

$$I_{L_1} = \frac{12000}{120} = 100 A$$

$$I_{f_1} = \frac{V_L}{R_{f_1}} = \frac{12D}{50} = 2.4 A$$

$$I_{n_1} = I_{n_1} - I_{f_1} = 100 - 2.4 = 92.6 \text{ A}$$

$$\phi_1 I_{\alpha_1} = K \phi_2 I$$

$$I_{n2} = \frac{\phi_1}{\phi_2} I_{n_1}$$

$$\frac{\phi_{1}}{\phi_{2}} = \frac{I_{f_{1}}}{I_{f_{2}}} = \frac{V_{L}/R_{f_{1}}}{V_{L}/R_{f_{2}}} = \frac{R_{f_{2}}}{R_{f_{1}}} = \frac{60}{50} = 1.2$$

$$I_{a_2} = \frac{\phi_1}{\phi_2} I_{a_1} = 1.2 \times 97.6 = 117.12 A$$